



VIA GIULIO PASTORE, 20
10024 MONCALIERI (TO)
Tel. 011 3400911 - Fax 011 3400921
www.dekra-automotivesolutions.com

CLIENTE:
ALD Automotive Italia S.r.l. a socio unico
VIALE LUCA GAURICO 187
00143 - Roma

DATA PERIZIA 29/06/2026	LOCALITA' GLM , Viale Porto Torres, 125, 7100, Sassari (SS)														
VEICOLO (MARCA - MODELLO - VERSIONE) LAND ROVER RANGE ROVER EVOQUE 2.0 D163 MHEV R-Dynamic S AWD auto Sport u					TARGA GG698ZX		TELAIO SALZA2BN9NH163241		1° IMMATRICOLAZ. 21/10/2021						
KM. 104988	COLORE. Santorini Black			TIPO SMALTO METALL/DOPPIO											
CODICE PARTE	VOCI DI DANNO LISTINO RICAMBI AGGIORNATO AL	SR		LA		VE		ME		PREZZO LISTINO	DCMS %	RICAMBI IVA esclusa			
		Diff.	TEMPO	Diff.	TEMPO	Diff.	TEMPO	Diff.	TEMPO						
	Pneum. ant sx Danneggiato														
	Pneum. ant dx Danneggiato														
	Disco ruota anteriore dx danneggiato									80,00		80,00			
	Disco ruota posteriore dx danneggiato									80,00		80,00			
	Carta di circolazione									150,00		150,00			
	Revisione ministeriale									64,77		64,77			
0362	#PRM# Calotta retrovisore est. SX														
1981	Paraurti ant. P/assist.parch.	L	1,40	L		L	2,10								
1981	Scomposizione paraurti		1,20												
1935	Parafango ant. DX	L		L	1,00	L	1,00								
2168	Porta ant. DX	L	1,30	L	0,50	L	1,60								
1552	Modanatura inf. porta ant. primer/nero narvik DX	S		S		S				221,71	S17	184,02			
2187	Porta post. DX	L	1,30	L	1,20	L	1,60								
1553	Modanatura inf. porta post. primer/nero narvik DX	S		S		S				184,81	S17	153,39			
1992	Paraurti post.	L	0,60	L		L	1,90								
1992	Scomposizione paraurti		1,30												
2209	Portello post.	L	0,35	L		L	1,20								
2636	Rivestimento paraurti post. t.LH999999<	S		S		S				143,76	S17	119,32			
2187	#PRM# Porta post. SX														
	Campagna di richiamo da eseguire									0,01		0,01			
TOTALE TEMPI		SR 7,45		LA 2,70		VE 9,40		ME 0,00		TOTALE RICAMBI 831,51					
ORE SUPPLEMENTO DOPPIO STRATO 15 %		1,41		ORE SUPPLEMENTO FINITURA 10 % MAX 3 ORE		1,08		ORE AGGIUNTIVE PER VERNICIATURA		1,60		TOTALE ORE SUPPLEMENTARI	4,09	TOTALE ORE VERNICIATURA	13,49
NOTE Pneumatico ant dx - Pirelli - 235/50/20 - multistagionale - 5.2 mm Pneumatico ant sx - Pirelli - 235/50/20 - multistagionale - 5.3 mm Pneumatico post dx - Pirelli - 235/50/20 - multistagionale - 5.4 mm Pneumatico post sx - Pirelli - 235/50/20 - multistagionale - 6 mm Veicolo sporco esternamente, Carta di circolazione originale non presente, Periziato con tempo sereno										RICAMBI		831,51			
										MATER. DI CONSUMO ORE 13,49 €/ORA 12,00		161,88			
										USO DIME		0,00			
										SMALTIMENTO RIFIUTI		24,69			
										MANODOPERA CARR. ORE 23,64 €/ORA 45,00		1063,80			
										MANODOPERA MECC. ORE 0,00 €/ORA 45,00		0,00			
										IMPONIBILE		2081,88			
										IVA		458,01			
										TOTALE COMPLESSIVO		2539,89			
CODICE PERITO 87		FIRMA			RUOLO N. 0000			FERMO TECNICO GIORNI 3			FOGLIO 1				

Legenda

FF:Forfait

PRM:Promemoria

DE:Difetto esecuzione

GR:Grandine

MAC:Macchiato

NU:Normale usura

SRG:Adesivi



VIA GIULIO PASTORE, 20
10024 MONCALIERI (TO)
Tel. 011 3400911 - Fax 011 3400921
www.dekra-automotivesolutions.com

CUSTOMER:
ALD Automotive Italia S.r.l. a socio unico
VIALE LUCA GAURICO 187
00143 - Roma

APPRAISAL DATE 29/06/2026	LOCATION GLM , Viale Porto Torres, 125, 7100, Sassari (SS)											
VEHICLE (BRAND - MODEL - VERSION) LAND ROVER RANGE ROVER EVOQUE 2.0 D163 MHEV R-Dynamic S AWD auto Sport u					PLATE GG698ZX		CHASSIS SALZA2BN9NH163241		1st REGISTRATION. 21/10/2021			
KM. 104988	COLOR. Santorini black			ENAMEL TYPE Metall/doppio								
PART CODE	ITEMS OF DAMAGE SPARE PARTS LIST UPDATED TO	SR		LA		VE		ME		PRICE LIST	DCMS SPARE PARTS % VAT excluded	
		Diff.	TIME	Diff.	TIME	Diff.	TIME	Diff.	TIME			
	Tire front left danneggiato											
	Tire front right danneggiato											
	Right front wheel damaged									80,00		80,00
	Right rear wheel damaged									80,00		80,00
	Registration certificate									150,00		150,00
	Periodic technical inspection									64,77		64,77
0362	#PRM# Ext. rear view mirror shell Sx											
1981	Paraurti front p/assist.parch.	L	1,40	L		L	2,10					
1981	Bumper dismantling		1,20									
1935	Front fender Dx	L		L	1,00	L	1,00					
2168	Front door Dx	L	1,30	L	0,50	L	1,60					
1552	Moulding lower brings front primer/nero narvik Dx	S		S		S				221,71	S17	184,02
2187	Rear door Dx	L	1,30	L	1,20	L	1,60					
1553	Moulding lower brings rear primer/nero narvik Dx	S		S		S				184,81	S17	153,39
1992	Rear bumper	L	0,60	L		L	1,90					
1992	Bumper dismantling		1,30									
2209	Tailgate	L	0,35	L		L	1,20					
2636	Coating bumper rear t.lh999999<	S		S		S				143,76	S17	119,32
2187	#PRM# Rear door Sx											
	Recall campaign to be performed									0,01		0,01
TOTAL TIMES		SR 7,45		LA 2,70		VE 9,40		ME 0,00		TOTAL SPARE PARTS 831,51		
DOUBLE LAYER SUPPLEMENT HOURS 15 % 1,41		FINISHING SUPPLEMENT HOURS 10 % MAX 3 HOURS 1,08		ADDITIONAL HOURS FOR PAINTING 1,60		TOTAL ADDITIONAL HOURS 4,09		TOTAL PAINTING HOURS 13,49				
NOTE Right front tire - Pirelli - 235/50/20 - Multistagionale - 5.2 mm Left front tire - Pirelli - 235/50/20 - Multistagionale - 5.3 mm Right rear tire - Pirelli - 235/50/20 - Multistagionale - 5.4 mm Left rear tire - Pirelli - 235/50/20 - Multistagionale - 6 mm Veicolo sporco esternamente , Paper from circulation originale not present , Appraised in clear weather						SPARE PARTS		831,51				
						MATER. CONSUMPTION HOURS 13,49€/HOUR 12,00		161,88				
						USE TEMPLATES		0,00				
						WASTING DISPOSAL		24,69				
						LABOR CARR. HOURS 23,64€/HOUR 45,00		1063,80				
						LABOR MECH. HOURS 0,00 €/HOUR 45,00		0,00				
						TAXABLE		2081,88				
						VAT		458,01				
						TOTAL		2539,89				
EXPERT CODE 87	SIGNATURE			ROLE NUMBER 0000		STOP TECHNICIAN DAYS 3			SHEET 1			

Legend

Ff: forfait

Prm: reminder

De: lack of execution

Gr: hail

Mac: stained

Nu: normal wear

Srg: stickers