



CLIENTE:
ALD Automotive Italia S.r.l. a socio unico
VIALE LUCA GAURICO 187
00143 - Roma

Legenda
FF:Forfait PRM:Promemoria DE:Difetto esecuzione GR:Grandine MAC:Macchiato NU:Normale usura SRG:Adesivi



VIA GIULIO PASTORE, 20
10024 MONCALIERI (TO)
Tel. 011 3400911 - Fax 011 3400921
www.dekra-automotivesolutions.com

CUSTOMER:
ALD Automotive Italia S.r.l. a socio unico
VIALE LUCA GAURICO 187
00143 - Roma

APPRAISAL DATE 22/07/2026	LOCATION CARROZZERIA ANGELO PELLEGATTA SRL , Via Luigi Fumagalli 2-6, 22066, MARIANO COMENSE (CO)											
VEHICLE (BRAND - MODEL - VERSION) MERCEDES SPRINTER (PC) 311 CDI F37/35 T.ALTO P.M. FP					PLATE GK228FV		CHASSIS W1V9076331P422861		1st REGISTRATION. 11/05/2022			
KM. 160307	COLOR. Mogano		ENAMEL TYPE Metall/doppio									
PART CODE	ITEMS OF DAMAGE SPARE PARTS LIST UPDATED TO	SR		LA		VE		ME		PRICE LIST	DCMS SPARE PARTS % VAT excluded	
		Diff.	TIME	Diff.	TIME	Diff.	TIME	Diff.	TIME			
	Periodic technical inspection									64,77		64,77
1981	Front bumper	S	1,30	S		S				508,23	S17	421,83
2000	Lateral rear bumper Sx	S	0,80	S		S				138,73	S17	115,15
1993	Centre rear bumper	S	0,30	S		S				357,69	S17	296,88
2012	Rear lateral wall Dx	L	0,80	M	2,45	L	5,90					
2187	Rear door Dx	M	1,10	M	2,45	M	4,00					
1733	Rear pillar Dx	L	1,00	L	1,00	L	1,30					
2006	Lateral wall Sx	M	0,35	M	2,45	M	5,90					
7908	Upper trim of front door perimeter substructure Sx	L	1,00	L	1,00	L	1,00					
7003	Ext. lateral cover of front seat cushion frame Sx	S	0,40	S		S				32,83	S17	27,25
1030	Front seat cushion upholstery Sx	S	0,70	S		S				217,45	S17	180,48
TOTAL TIMES			SR 7,75		LA 9,35		VE 18,10		ME 0,00		TOTAL SPARE PARTS 1106,36	
DOUBLE LAYER SUPPLEMENT HOURS 15 % 2,72		FINISHING SUPPLEMENT HOURS 10 % MAX 3 HOURS 2,08		ADDITIONAL HOURS FOR PAINTING 1,60		TOTAL ADDITIONAL HOURS 6,40		TOTAL PAINTING HOURS 24,50				
NOTE Right front tire - Kleber - 235/65/16 - Summer - 5 mm Left front tire - Kleber - 235/65/16 - Summer - 5 mm Right rear tire - Kleber - 235/65/16 - Summer - 5 mm Left rear tire - Kleber - 235/65/16 - Summer - 5 mm Low battery, Veicolo sporco esternamente , Vehicle with special equipment, Appraised in clear weather								SPARE PARTS		1106,36		
								MATER. CONSUMPTION HOURS 24,50€/HOUR 12,00		294,00		
								USE TEMPLATES		0,00		
								WASTING DISPOSAL		25,00		
								LABOR CARR. HOURS 41,60€/HOUR 45,00		1872,00		
								LABOR MECH. HOURS 0,00 €/HOUR 45,00		0,00		
								TAXABLE		3297,36		
								VAT		725,42		
								TOTAL		4022,78		
EXPERT CODE 111	SIGNATURE			ROLE NUMBER 0000		STOP TECHNICIAN DAYS 6			SHEET 1			

Legend

Ff: forfait

Prm: reminder

De: lack of execution

Gr: hail

Mac: stained

Nu: normal wear

Srg: stickers