



Via Fratelli Gracchi 27
20092 Cinisello Balsamo (MI)
www.dekra-automotivesolutions.com

CLIENTE:
ALD Automotive Italia S.r.l. a socio unico
VIALE LUCA GAURICO 187
00143 - Roma

DATA PERIZIA 03/08/2026	LOCALITA' BRASIELLO CARSERVICE SRL , Viale Corsica 21, 20133, MILANO (MI)															
VEICOLO (MARCA - MODELLO - VERSIONE) BMW X3 xDrive 30e Sport utility vehicle 5-door (Euro 6D)						TARGA GK070FT		TELAIO WBA61DP0409L90856		1° IMMATRICOLAZ. 09/05/2022						
KM. 111846	COLORE. Skyscraper Grey			TIPO SMALTO METALL/DOPPIO												
CODICE PARTE	VOCI DI DANNO LISTINO RICAMBI AGGIORNATO AL	SR		LA		VE		ME		PREZZO LISTINO	DCMS %	RICAMBI IVA esclusa				
		Diff.	TEMPO	Diff.	TEMPO	Diff.	TEMPO	Diff.	TEMPO							
	SOH									0,01		0,01				
	Disco ruota anteriore sx danneggiato									80,00		80,00				
	Disco ruota posteriore dx danneggiato									80,00		80,00				
1981	#PRM# Paraurti ant. P/assist.parch. primer															
1992	#PRM# Paraurti post. P/Kit M/assist.parch. primer															
NOTE Pneumatico ant dx - Pirelli - 245/45/20 - estivo - 5 mm Pneumatico ant sx - Pirelli - 245/45/20 - estivo - 5 mm Pneumatico post dx - Pirelli - 245/45/20 - estivo - 5 mm Pneumatico post sx - Pirelli - 245/45/20 - estivo - 5 mm Cavo di ricarica domestico presente, Cavo di ricarica per colonnina presente, CDC copia conforme, Periziato con tempo sereno																
													RICAMBI		160,01	
													MATER. DI CONSUMO ORE 0,00 € /ORA 12,00		0,00	
													USO DIME		0,00	
													SMALTIMENTO RIFIUTI		1,92	
MANODOPERA CARR. ORE 0,00 € /ORA 45,00		0,00														
MANODOPERA MECC. ORE 0,00 € /ORA 45,00		0,00														
IMPONIBILE		161,93														
IVA		35,62														
TOTALE COMPLESSIVO		197,55														
CODICE PERITO 46	FIRMA			RUOLO N. 0000		FERMO TECNICO GIORNI 0			FOGLIO 1							

Legenda

FF:Forfait

PRM:Promemoria

DE:Difetto esecuzione

GR:Grandine

MAC:Macchiato

NU:Normale usura

SRG:Adesivi



Via Fratelli Gracchi 27
20092 Cinisello Balsamo (MI)
www.dekra-automotivesolutions.com

CUSTOMER:
ALD Automotive Italia S.r.l. a socio unico
VIALE LUCA GAURICO 187
00143 - Roma

APPRAISAL DATE 03/08/2026	LOCATION BRASIELLO CARSERVICE SRL , Viale Corsica 21, 20133, MILANO (MI)											
VEHICLE (BRAND - MODEL - VERSION) BMW X3 xDrive 30e Sport utility vehicle 5-door (Euro 6D)						PLATE GK070FT		CHASSIS WBA61DP0409L90856		1st REGISTRATION. 09/05/2022		
KM. 111846	COLOR. Skyscraper grey			ENAMEL TYPE Metall/doppio								
PART CODE	ITEMS OF DAMAGE SPARE PARTS LIST UPDATED TO	SR		LA		VE		ME		PRICE LIST	DCMS SPARE PARTS % VAT excluded	
		Diff.	TIME	Diff.	TIME	Diff.	TIME	Diff.	TIME			
	Soh									0,01		0,01
	Left front wheel damaged									80,00		80,00
	Right rear wheel damaged									80,00		80,00
1981	#PRM# Paraurti front p/assist.parch. primer											
1992	#PRM# Paraurti rear p/kit m/assist.parch. primer											
TOTAL TIMES		SR 0,00		LA 0,00		VE 0,00		ME 0,00		TOTAL SPARE PARTS 160,01		
DOUBLE LAYER SUPPLEMENT HOURS 15 % 0,00		FINISHING SUPPLEMENT HOURS 10 % MAX 3 HOURS 0,00		ADDITIONAL HOURS FOR PAINTING 0,00		TOTAL ADDITIONAL HOURS 0,00		TOTAL PAINTING HOURS 0,00				
NOTE Right front tire - Pirelli - 245/45/20 - Summer - 5 mm Left front tire - Pirelli - 245/45/20 - Summer - 5 mm Right rear tire - Pirelli - 245/45/20 - Summer - 5 mm Left rear tire - Pirelli - 245/45/20 - Summer - 5 mm Cavo from charging domestico present , Cavo from charging for colonnina present , Cdc copia compliant , Appraised in clear weather								SPARE PARTS		160,01		
								MATER. CONSUMPTION HOURS 0,00 €/HOUR 12,00		0,00		
								USE TEMPLATES		0,00		
								WASTING DISPOSAL		1,92		
								LABOR CARR. HOURS 0,00 €/HOUR 45,00		0,00		
								LABOR MECH. HOURS 0,00 €/HOUR 45,00		0,00		
								TAXABLE		161,93		
								VAT		35,62		
								TOTAL		197,55		
EXPERT CODE 46	SIGNATURE			ROLE NUMBER 0000		STOP TECHNICIAN DAYS 0			SHEET 1			

Legend
Ff: forfait Prm: reminder De: lack of execution Gr: hail Mac: stained Nu: normal wear Srg: stickers